

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

## **REGION IX**

## 215 Fremont Street San Francisco, Ca. 94105

2/18/87

RE: Return of Part A Hazardous Waste Permit Application - Missing or Incomplete Information

The Environmental Protection Agency (EPA) has reviewed your Part A of the RCRA permit application for the facility referenced above. The items checked below have been found missing or insufficient for the purposes of our review.

Core information Forms 1	and 3		
Facility name	Operato	r Information	Location
Mail Address	Y Process	Information	Owner
Certification	Waste I	nformation	ITEM 2 15 GATIONS
Signature, date			2
<u>See</u>	Page 10	F5/ Iter	n 2
UNITS	MUST BE		
Non-core information for		TOATA	EFT OFF PART
Photographs. Must existing storage, to future storage, cate EPA ID number	treatment and	neate all existir disposal process d disposal proces	ng structures, management of the structures, and sites $\mathcal{H}_{0}$ and $\mathcal{H}_{0}$ and $\mathcal{H}_{0}$ and $\mathcal{H}_{0}$ and $\mathcal{H}_{0}$ and $\mathcal{H}_{0}$ are structures, and sites $\mathcal{H}_{0}$ are structures, an
Facility Drawing. including current, disposal processes. daries and storage, their dimensions pr	past and/or f Drawing sho treatment ar	uture storage, to ould be <u>to scale</u> nd disposal proce	reatment and with the boun-
Map. Must be topogr property boundaries should be clearly m Maps can be obtaine	of the facil arked on the	lity. <u>Location</u> of map. Indicate F	of the facility EPA ID # on map. Survey Office Road
Coordinates. Longi	tude and Lati	itude of the fact	ility must be
Please return the Part A and requested information		U.S. EPA RCRA Program Sec 215 Fremont Stre	eet

Lucy Mlenar

ŀ	C		_		DU	P 13 14	1 15	7		$\overline{}$		_	7		$\sqrt{}$	.\	΄,	///	$\sqrt{}$			$\int$						/ /
	ĸ	CEBS CODE (from list above)		ο-	В.	B. PROCESS DESIGN CAPACITY										. PRO-		B. PROCESS DESIGN CAPACITY										
	LINE			S E list:		1. AMOUNT (specify)		2. UNIT OF MEA- SURE (enter code)			FOR OFFICIAL USE ONLY			LINE	(from list above)		is E list e)							2, UNIT OF MEA SURE (enter code)		<b>A</b> -	OF!	FOR FFICIA USE ONLY
	X-1	16 C		2		600	27		20	21	T	Ť	32	5		0	4		0.375	<u>.                                    </u>			27	-	D	-	1	Ťī
-	Λ-1	3	U	2	ļ	000			G	+	4	+	+	2	1	U	4	ļ	0.575					1		-	4	44
	X-2	T	0	3		20			E					6														
	1	s	0	1		46,695			G					7														
	2)	s	0	1		567			G		$\Big)$			8														
	3	s	0	4		100,000			G					9														
	4	Т	0	1		200			U					10										T			T	
		16	_		19		27	_	28	_ 7	_	-:	32		16		18	19		-			27	1_	28		29	_:
	EP/	A F	orm	35	10-3 (6-80	1						РΔ	GE	10	_	<b>E</b>												